



















## Summary of Study Report with Pictures







Sr. No.	Date Of Visit	Village	Work	No. Of Work	Sanction Year	Estimated Cost	Actual Coat	Technical Santional No.	Administrative Santion No.	Work Order	Work Start Date	Working Agency	Estimated Measurement	MB Measurement	Actual Measurement	Work Quality	Observation	Recomandatio n	Photo
1	1.3.2019	KAWTHA	Dhaliche Bandh	III/1	2017-18	2.62	1.56	683/20.2.2018	1361/27.2.2018	770/4.4.2018	23.4.2018	NANASAHAB SAMRAT	L. 1866.40 MI	L. 817.60 MI	L. 817.60 MI	GOOD	Increase ground water level.	Regular Destilting. Removal of Vegetation.	
2	1.3.2019	KAWTHA	Dhaliche Bandh	III/2	2017-18	5.29	1.32	684/20.2.2018	1361/1.2.2018	770/4.4.2018	25.4.2018	NANASAHAB SAMRAT	L. 9460 MI	L. 1650 MI	L. 1650 MI	GOOD	Increase in soil moisture.	Bunds should be constructing across the slope.	
3	1.3.2019	KAWTHA	Dhaliche Bandh	III/3	2017-18	5.02	1.82	685/20.2.2018	1361/1.2.2018	770/4.4.2018	25.4.2018	NANASAHAB SAMRAT	L. 4170 MI	L. 1340 MI	L. 1340 MI	GOOD	Decrease in soil runoff.	Regular Destilting. Removal of Vegetation.	
4	1.3.2019	KAWTHA	Dhaliche Bandh	III/4	2017-18	3.08	1.69	686/20.2.2018	1361/27.2.2018	770/4.4.2018	27.4.2018	NANASAHAB SAMRAT	L. 3260 MI	L. 1160 MI	L. 1160 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	
5	1.3.2019	KAWTHA	Dhaliche Bandh	III/5	2017-18	5.92	1.66	687/20.2.2018	1361/27.2.2018	770/4.4.2018	27.4.2018	NANASAHAB SAMRAT	L. 2068 MI	L. 510 MI	L. 510 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	
6	1.3.2019	KAWTHA	Gabion	III/1	2017-18	0.19	0.21	714/26.2.2018	1563/3.5.2018	770/17.5.2018	27.5.2018	NITESH JAGNALHE	L. 10. H. 1 MI	L. 10. H. 1 MI	L. 10. H. 1 MI	GOOD	The gabion was properly formed.	Regular Destilting. Removal of Vegetation.	

Sr. No.	Date Of Visit	Village	Work	No. Of Work	Sanction Year	Estimated Cost	Actual Cost	Technical Santional No.	Administrative Santion No.	Work Order	Work Start Date	Working Agency	Estimated Measurement	MB Measurement	Actual Measurement	Work Quality	Observation	Recomandatio n	Photo
7	1.3.2019	KAWTHA	Gabion	III/2	2017-18	0.19	0.23	714/26.2.2018	1563/3.5.2018	770/17.5.2018	29.5.2018	NITESH JAGNALHE	L. 10, H. 1 MI	L. 10, H. 1 MI	L. 10, H. 1 MI	GOOD	Useful for raising soil and waste.	Give more structure for water consevation.	
8	1.3.2019	KAWTHA	Nala Deepening	III/1	2017-18	0.83	0.76	620/24.1.2018	771/1.2.2018	598/22.3.2018	16.4.2018	ULHASH SAIWALE	L. 250 MI	L. 250 MI	L. 250 MI	GOOD	This work will benefit the farmers.	Give more structure for water consevation.	
9	1.3.2019	KAWTHA	Nala Deepening	III/2	2017-18	0.98	0.73	621/24.1.2018	771/1.2.2018	598/22.3.2018	19.4.2018	ULHASH SAIWALE	L. 250 MI	L. 250 MI	L. 250 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	
10	1.3.2019	KAWTHA	Nala Deepening	III/3	2017-18	0.77	0.73	622/24.1.2018	771/1.2.2018	598/22.3.2018	23.4.2018	HEMANT NETKE	L. 200 MI	L. 200 MI	L. 200 MI	GOOD	Increase water level.	Handover to user group.	
11	1.3.2019	SONEGAW BORI	Nala Deepening	I/1	2017-18	1	0.79	623/24.1.2018	771/1.2.2018	749/31.3.2018	13.4.2018	R. R. JUNEJA	L. 260 MI	L. 260 MI	L. 260 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	
12	1.3.2019	SONEGAW BORI	Nala Deepening	I/2	2017-18	0.83	0.58	624/24.1.2018	771/1.2.2018	751/31.3.2018	13.4.2018	V. B. BANSOD	L. 120 MI	L. 120 MI	L. 120 MI	GOOD	Increase ground water level.	Regular Destilting. Removal of Vegetation.	









Sr. No.	Date Of Visit	Village	Work	No. Of Work	Sanction Year	Estimated Cost	Actual Cost	Technical Santional No.	Administrative Santion No.	Work Order	Work Start Date	Working Agency	Estimated Measurement	MB Measurement	Actual Measurement	Work Quality	Observation	Recomandatio n	Photo
13	1.3.2019	SONEGAW BORI	Nala Deepening	I/3	2017-18	0.94	0.69	625/24.1.2018	771/1.2.2018	751/31.3.2018	8.4.2018	V. B. BANSOD	L. 160 MI	L. 160 MI	L. 160 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	
14	1.3.2019	SONEGAW BORI	Nala Deepening	I/4	2017-18	0.84	0.81	626/24.1.2018	771/1.2.2018	750/31.3.2018	11.4.2018	R. R. JUNEJA	L. 360 MI	L. 360 MI	L. 360 MI	GOOD	Proper Execution. Work is as per Technical Specification. la deepening is done	Handover to user group.	
15	1.3.2019	SONEGAW BORI	Nala Deepening	I/5	2017-18	0.98	0.93	627/24.1.2018	771/1.2.2018	750/31.3.2018	12.4.2018	SURMIT JUNEJA	L. 340 MI	L. 340 MI	L. 340 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	
16	1.3.2019	CHICKKUTHA	Dhaliche Bandh	V/1	2017-18	2.58	0.17	688/20.2.2018	548/18.4.2018	803/4.4.2018	26.5.2018	PRANAY BHANDARKAR	L. 4170 MI	L. 1340 MI	L. 1340 MI	GOOD	deepening of the drain will provide water for irrigation.	make provision to board.	
17	1.3.2019	CHICKKUTHA	Dhaliche Bandh	V/2	2017-18	2.6	0.96	689/20.2.2018	548/18.4.2018	803/4.4.2018	29.5.2018	PRANAY BHANDARKAR	L. 3260 MI	L. 1160 MI	L. 1160 MI	GOOD	Increase in soil moisture.	Bunds should be constructing across the slope.	
18	1.3.2019	CHICKKUTHA	Dhaliche Bandh	V/3	2017-18	1.81	0.43	690/20.2.2018	548/18.4.2018	803/4.4.2018	1.1.2018	PRANAY BHANDARKAR	L. 2068 MI	L. 510 MI	L. 510 MI	GOOD	Decrease in soil runoff.	Regular Destilting. Removal of Vegetation.	















Sr. No.	Date Of Visit	Village	Work	No. Of Work	Sanction Year	Estimated Cost	Actual Cost	Technical Santional No.	Administrative Santion No.	Work Order	Work Start Date	Working Agency	Estimated Measurement	MB Measurement	Actual Measurement	Work Quality	Observation	Recomandatio n	Photo
19	1.3.2019	CHICKKUTHA	L. B. S.	1	2017-18	0.29	0.2	741/31.5.2018	3987/1.6.2018	1539/14.6.2018	25.6.2018	NITESH JAGNALHE	L. 8, H. 1 MI	L. 8, H. 1 MI	L. 8, H. 1 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	
20	1.3.2019	CHICKKUTHA	L. B. S.	2	2017-18	0.29	0.2	741/31.5.2018	3987/1.6.2018	1539/14.6.2018	25.6.2018	NITESH JAGNALHE	L. 10, H. 1 MI	L. 10, H. 1 MI	L. 10, H. 1 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	
21	1.3.2019	CHICKKUTHA	L. B. S.	3	2017-18	0.29	0.2	741/31.5.2018	3987/1.6.2018	1539/14.6.2018	25.6.2018	NITESH JAGNALHE	L. 8, H. 1 MI	L. 8, H. 1 MI	L. 8, H. 1 MI	GOOD	The gabion was properly formed.	Regular Destilting. Removal of Vegetation.	
22	1.3.2019	CHICKKUTHA	L. B. S.	4	2017-18	0.29	0.2	741/31.5.2018	3987/1.6.2018	1539/14.6.2018	25.6.2018	NITESH JAGNALHE	L. 10, H. 1 MI	L. 10, H. 1 MI	L. 10, H. 1 MI	GOOD	Useful for raising soil and waste.	Give more structure for water consevation.	
23	1.3.2019	CHICKKUTHA	L. B. S.	5	2017-18	0.29	0.2	741/31.5.2018	3987/1.6.2018	1539/14.6.2018	25.6.2018	NITESH JAGNALHE	L. 8, H. 1 MI	L. 8, H. 1 MI	L. 8, H. 1 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	
24	1.3.2019	CHICKKUTHA	L. B. S.	6	2017-18	0.29	0.2	741/31.5.2018	3987/1.6.2018	1539/14.6.2018	25.6.2018	NITESH JAGNALHE	L. 10, H. 1 MI	L. 10, H. 1 MI	L. 10, H. 1 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	









Sr. No.	Date Of Visit	Village	Work	No. Of Work	Sanction Year	Estimated Cost	Actual Cost	Technical Santional No.	Administrative Santion No.	Work Order	Work Start Date	Working Agency	Estimated Measurement	MB Measurement	Actual Measurement	Work Quality	Observation	Recomandatio n	Photo
25	1.3.2019	KINHADMADKI	L. B. S.	1	2017-18	0.3	0.34	743/31.5.2018	3987/1.6.2018	3252/27.11.2018	8.12.2018	NITESH JAGNALHE	L. 8, H. 1 MI	L. 8, H. 1 MI	L. 8, H. 1 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	
26	1.3.2019	KINHADMADKI	L. B. S.	2	2017-18	0.3	0.34	743/31.5.2018	3987/1.6.2018	3252/27.11.2018	8.12.2018	NITESH JAGNALHE	L. 10, H. 1 MI	L. 10, H. 1 MI	L. 10, H. 1 MI	GOOD	The gabion was properly formed.	Regular Destilting. Removal of Vegetation.	
27	1.3.2019	KINHADMADKI	L. B. S.	3	2017-18	0.3	0.34	743/31.5.2018	3987/1.6.2018	3252/27.11.2018	8.12.2018	NITESH JAGNALHE	L. 8, H. 1 MI	L. 8, H. 1 MI	L. 8, H. 1 MI	GOOD	Useful for raising soil and waste.	Give more structure for water consevation.	
28	1.3.2019	KINHADMADKI	L. B. S.	4	2017-18	0.3	0.34	743/31.5.2018	3987/1.6.2018	3252/27.11.2018	8.12.2018	NITESH JAGNALHE	L. 10, H. 1 MI	L. 10, H. 1 MI	L. 10, H. 1 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	
29	1.3.2019	KINHADMADKI	L. B. S.	5	2017-18	0.3	0.34	743/31.5.2018	3987/1.6.2018	3252/27.11.2018	8.12.2018	NITESH JAGNALHE	L. 8, H. 1 MI	L. 8, H. 1 MI	L. 8, H. 1 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	
30	1.3.2019	KINHADMADKI	L. B. S.	6	2017-18	0.3	0.34	743/31.5.2018	3987/1.6.2018	3252/27.11.2018	8.12.2018	NITESH JAGNALHE	L. 8, H. 1 MI	L. 8, H. 1 MI	L. 8, H. 1 MI	GOOD	The gabion was properly formed.	Regular Destilting. Removal of Vegetation.	









Sr. No.	Date Of Visit	Village	Work	No. Of Work	Sanction Year	Estimated Cost	Actual Cost	Technical Santional No.	Administrative Santion No.	Work Order	Work Start Date	Working Agency	Estimated Measurement	MB Measurement	Actual Measurement	Work Quality	Observation	Recomandatio n	Photo
31	2.3.2019	KINHADMADKI	L. B. S.	7	2017-18	0.3	0.34	743/31.5.2018	3987/1.6.2018	3252/27.11.2018	8.12.2018	NITESH JAGNALHE	L. 8, H. 1 MI	L. 8, H. 1 MI	L. 8, H. 1 MI	GOOD	Useful for raising soil and waste.	Give more structure for water consevation.	
32	2.3.2019	MOHGAW TA.	L. B. S.	1	2017-18	0.15	0.093	742/31.5.2018	3987/1.6.2018	1539/14.6.2018	25.6.2018	NITESH JAGNALHE	L. 8, H. 1 MI	L. 8, H. 1 MI	L. 8, H. 1 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	
33	2.3.2019	MOHGAW TA.	L. B. S.	2	2017-18	0.15	0.093	742/31.5.2018	3987/1.6.2018	1539/14.6.2018	25.6.2018	NITESH JAGNALHE	L. 8, H. 1 MI	L. 8, H. 1 MI	L. 8, H. 1 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	
34	2.3.2019	TEMBHARI	Nala Deepening	1	2017-18	1.04	1.09	660/1.2.2018	838/5.2.2018	2016/21.4.2018	4.5.2018	NISHANT DEWLHE	L. 300 MI	L. 160 MI	L. 160 MI	GOOD	This work will benefit the farmers.	Regular Destilting. Removal of Vegetation.	
35	2.3.2019	TEMBHARI	Nala Deepening	2	2017-18	0.86	0.83	661/1.2.2018	838/5.2.2018	2016/21.4.2018	6.5.2018	NISHANT DEWLHE	L. 250 MI	L. 250 MI	L. 250 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Give more structure for water consevation.	
36	2.3.2019	TEMBHARI	Nala Deepening	3	2017-18	5.93	3.8	398/13.4.2017	548/19.4.2017	1366/17.5.2017	24.5.2018	NISHANT DEWLHE	L. 260 MI	L. 220 MI	L. 220 MI	GOOD	Increase water level.	Handover to user group.	

Sr. No.	Date Of Visit	Village	Work	No. Of Work	Sanction Year	Estimated Cost	Actual Cost	Technical Santional No.	Administrative Santion No.	Work Order	Work Start Date	Working Agency	Estimated Measurement	MB Measurement	Actual Measurement	Work Quality	Observation	Recomandatio n	Photo
37	2.3.2019	TEMBHARI	Nala Deepening	4	2017-18	5.39	3.51	399/13.4.2017	548/19.4.2017	1366/17.5.2017	28.5.2018	NISHANT DEWLHE	L. 260 MI	L. 240 MI	L. 240 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	
38	2.3.2019	TEMBHARI	L. B. S.	1	2017-18	0.23	0.21	740/31.5.2018	3979/1.6.2018	1539/14.6.2018	16.6.2018	NITESH JAGNALHE	L. 8, H. 1 MI	L. 8, H. 1 MI	L. 8, H. 1 MI	GOOD	The gabion was properly formed.	Regular Destilting. Removal of Vegetation.	
39	2.3.2019	TEMBHARI	L. B. S.	2	2017-18	0.23	0.21	740/31.5.2018	3979/1.6.2018	1539/14.6.2018	16.6.2018	NITESH JAGNALHE	L. 8, H. 1 MI	L. 8, H. 1 MI	L. 8, H. 1 MI	GOOD	Useful for raising soil and waste.	Give more structure for water consevation.	
40	2.3.2019	TEMBHARI	L. B. S.	3	2017-18	0.23	0.21	740/31.5.2018	3979/1.6.2018	1539/14.6.2018	16.6.2018	NITESH JAGNALHE	L. 8, H. 1 MI	L. 8, H. 1 MI	L. 8, H. 1 MI	GOOD	The gabion was properly formed.	Regular Destilting. Removal of Vegetation.	
41	2.3.2019	TEMBHARI	L. B. S.	4	2017-18	0.23	0.21	740/31.5.2018	3979/1.6.2018	1539/14.6.2018	16.6.2018	NITESH JAGNALHE	L. 8, H. 1 MI	L. 8, H. 1 MI	L. 8, H. 1 MI	GOOD	Useful for raising soil and waste.	Give more structure for water consevation.	
42	2.3.2019	TEMBHARI	L. B. S.	5	2017-18	0.23	0.21	740/31.5.2018	3979/1.6.2018	1539/14.6.2018	16.6.2018	NITESH JAGNALHE	L. 8, H. 1 MI	L. 8, H. 1 MI	L. 8, H. 1 MI	GOOD	The gabion was properly formed.	Regular Destilting. Removal of Vegetation.	









Sr. No.	Date Of Visit	Village	Work	No. Of Work	Sanction Year	Estimated Cost	Actual Cost	Technical Santional No.	Administrative Santion No.	Work Order	Work Start Date	Working Agency	Estimated Measurement	MB Measurement	Actual Measurement	Work Quality	Observation	Recomandatio n	Photo
43	2.3.2019	TEMBHARI	L. B. S.	6	2017-18	0.23	0.21	740/31.5.2018	3979/1.6.2018	1539/14.6.2018	16.6.2018	NITESH JAGNALHE	L. 8, H. 1 MI	L. 8, H. 1 MI	L. 8, H. 1 MI	GOOD	Useful for raising soil and waste.	Give more structure for water consevation.	
44	2.3.2019	TEMBHARI	L. B. S.	7	2017-18	0.23	0.21	740/31.5.2018	3979/1.6.2018	1539/14.6.2018	16.6.2018	NITESH JAGNALHE	L. 8, H. 1 MI	L. 8, H. 1 MI	L. 8, H. 1 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	
45	2.3.2019	TEMBHARI	L. B. S.	8	2017-18	0.23	0.21	740/31.5.2018	3979/1.6.2018	1539/14.6.2018	16.6.2018	NITESH JAGNALHE	L. 8, H. 1 MI	L. 8, H. 1 MI	L. 8, H. 1 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	
46	2.3.2019	AALAGONDI	L. B. S.	VI/1	2017-18	0.14	0.033	734/9.3.2018	1563/5.3.2018	1331/23.5.2018	21.6.2018	NISHANT DEWLHE	L. 8, H. 1 MI	L. 8, H. 1 MI	L. 8, H. 1 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	
47	2.3.2019	AALAGONDI	L. B. S.	VI/2	2017-18	0.14	0.033	739/9.3.2018	3987/1.6.2018	1539/14.4.2018	21.6.2018	NISHANT DEWLHE	L. 8, H. 1 MI	L. 8, H. 1 MI	L. 8, H. 1 MI	GOOD	The gabion was properly formed.	Regular Destilting. Removal of Vegetation.	
48	2.3.2019	AALAGONDI	L. B. S.	VI/3	2017-18	0.14	0.032	739/9.3.2018	3987/1.6.2018	1539/14.4.2018	21.6.2018	NISHANT DEWLHE	L. 8, H. 1 MI	L. 8, H. 1 MI	L. 8, H. 1 MI	GOOD	Useful for raising soil and waste.	Give more structure for water consevation.	















Sr. No.	Date Of Visit	Village	Work	No. Of Work	Sanction Year	Estimated Cost	Actual Cost	Technical Santional No.	Administrative Santion No.	Work Order	Work Start Date	Working Agency	Estimated Measurement	MB Measurement	Actual Measurement	Work Quality	Observation	Recomandatio n	Photo
49	2.3.2019	AALAGONDI	L. B. S.	VI/4	2017-18	0.14	0.032	739/9.3.2018	3987/1.6.2018	1539/14.4.2018	21.6.2018	NISHANT DEWLHE	L. 8, H. 1 MI	L. 8, H. 1 MI	L. 8, H. 1 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	
50	2.3.2019	AALAGONDI	FORM POND	123	2017-18	0.5	0.5	181/17.3.2017	737/17.3.2017	1167/20.3.2017	19.4.2017	FORMAR	L.25,W.20,D.3 MI	L.25,W.20,D.3 MI	L.25,W.20,D.3 MI	GOOD	Helpful for supportive irrigation.	Regular Destilting. Removal of Vegetation.	
51	2.3.2019	AALAGONDI	FORM POND	169	2017-18	0.5	0.5	179/17.3.2017	767/17.3.2017	1165/20.3.2017	15.4.2017	FORMAR	L.25,W.20,D.3 MI	L.25,W.20,D.3 MI	L.25,W.20,D.3 MI	GOOD	Former use the pond for fishary for supportive income.	Give more structure for water consevation.	
52	2.3.2019	AALAGONDI	FORM POND	174	2017-18	0.5	0.5	182/17.3.2017	867/17.3.2017	1166/20.3.2017	10.4.2017	FORMAR	L.25,W.20,D.3 MI	L.25,W.20,D.3 MI	L.25,W.20,D.3 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	
53	2.3.2019	AALAGONDI	Nala Deepening	1	2017-18	4.19	2.7	400/13.4.2017	548/18.4.2017	1366/17.5.2017	17.5.2017	NISHANT DEWLHE	L. 260 MI	L. 260 MI	L. 260 MI	GOOD	This work will benefit the farmers.	Regular Destilting. Removal of Vegetation.	
54	2.3.2019	AALAGONDI	Nala Deepening	2	2017-18	4.28	2.74	401/13.4.2017	548/18.4.2017	1366/17.5.2017	20.5.2017	SHRI SAI INFO.	L. 260 MI	L. 260 MI	L. 260 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Give more structure for water consevation.	









Sr. No.	Date Of Visit	Village	Work	No. Of Work	Sanction Year	Estimated Cost	Actual Cost	Technical Santional No.	Administrative Santion No.	Work Order	Work Start Date	Working Agency	Estimated Measurement	MB Measurement	Actual Measurement	Work Quality	Observation	Recomandatio n	Photo
55	2.3.2019	AALAGONDI	Nala Deepening	4	2017-18	0.43	0.48	656/1.2.2018	838/5.2.2018	469/20.3.2018	2.5.2018	NISHANT DEWLHE	L. 230 MI	L. 230 MI	L. 230 MI	GOOD	Increase water level.	Handover to user group.	
56	2.3.2019	AALAGONDI	Nala Deepening	5	2017-18	0.41	0.38	657/1.2.2018	838/5.2.2018	748/31.3.2018	13.4.2018	NAVNI ARTHMUVERS	L. 130 MI	L. 120 MI	L. 120 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	
57	2.3.2019	AALAGONDI	Nala Deepening	6	2017-18	0.32	0.29	658/1.2.2018	838/5.2.2018	748/31.3.2018	13.4.2018	NAVNI ARTHMUVERS	L. 130 MI	L. 130 MI	L. 130 MI	GOOD	Increase ground water level.	Regular Destilting. Removal of Vegetation.	
58	2.3.2019	AALAGONDI	Nala Deepening	7	2017-18	0.42	0.47	659/1.2.2018	838/5.2.2018	748/31.3.2018	13.4.2018	R. R. JUNEJA	L. 85 MI	L. 40 MI	L. 40 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	
59	2.3.2019	AALAGONDI	Gabion VI/1	VI/1	2017-18	0.4	0.19	734/3.3.2018	1563/5.3.2018	1331/23.5.2018	24.5.2018	NISHANT DEWLHE	L. 10, W. 1 MI	L. 10, W. 1 MI	L. 10, W. 1 MI	GOOD	Useful for redusing water flow.	Regular Destilting. Removal of Vegetation.	
60	2.3.2019	AALAGONDI	Gabion VI/1	VI/1	2017-18	0.4	0.19	735/9.3.2018	1563/5.3.2018	1331/23.5.2018	24.5.2018	NISHANT DEWLHE	L. 10, W. 1 MI	L. 10, W. 1 MI	L. 10, W. 1 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	









Sr. No.	Date Of Visit	Village	Work	No. Of Work	Sanction Year	Estimated Cost	Actual Cost	Technical Santional No.	Administrative Santion No.	Work Order	Work Start Date	Working Agency	Estimated Measurement	MB Measurement	Actual Measurement	Work Quality	Observation	Recomandatio n	Photo
61	3.2.2019	AALAGONDI	C.N.B. REPERING	VI/1	2017-18	0.18	0.16	720/3.3.2018	1563/5.3.2018	1331/23.5.2018	24.5.2018	NISHANT DEWLHE	L.3,W.1.35,H.1.50 MI	L.3,W.1.35,H.1.50 MI	L.3,W.1.35,H.1.50 MI	Poor	The main wall and the side wall are broken.	Main wall and side wall should be repaired properly.	
62	3.2.2019	AALAGONDI	C.N.B. REPERING	VI/2	2017-18	0.29	0.18	721/3.3.2018	1563/5.3.2018	1331/23.5.2018	25.5.2018	NISHANT DEWLHE	L.4,W.1.35,H.1.50 MI	L.4,W.1.35,H.1.50 MI	L.4,W.1.35,H.1.50 MI	Poor	The main wall and the side wall are broken.	Main wall and side wall should be repaired properly.	
63	3.2.2019	AALAGONDI	C.N.B. REPERING	VI/3	2017-18	0.3	0.27	722/3.3.2018	1563/5.3.2018	1331/23.5.2018	26.5.2018	NISHANT DEWLHE	L.6,W.1.35,H.1.50 MI	L.6,W.1.35,H.1.50 MI	L.6,W.1.35,H.1.50 MI	GOOD	the main wall was repaired properly.	Regular Destilting. Removal of Vegetation.	
64	3.2.2019	AALAGONDI	C.N.B. REPERING	VI/4	2017-18	0.25	0.25	723/3.3.2018	1563/5.3.2018	1331/23.5.2018	27.5.2018	NISHANT DEWLHE	L.5,W.1.35,H.1.50 MI	L.5,W.1.35,H.1.50 MI	L.5,W.1.35,H.1.50 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	
65	3.2.2019	AALAGONDI	C.N.B. REPERING	VI/5	2017-18	0.36	0.33	724/3.3.2018	1563/5.3.2018	1331/23.5.2018	28.5.2018	NISHANT DEWLHE	L.6,W.1.35,H.1.50 MI	L.6,W.1.35,H.1.50 MI	L.6,W.1.35,H.1.50 MI	GOOD	main wall and side cwall was repaired properly.	Handover to user group.	
66	3.2.2019	VHYADGHAT	Dhaliche Bandh	VI/1	2017-18	6.02	0.97	665/1.2.2018	838/5.2.2018	622/23.3.2018	1.6.2018	SANJAY BHISE	L. 3453.88 MI	L. 3453.88 MI	L. 3453.88 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	

Sr. No.	Date Of Visit	Village	Work	No. Of Work	Sanction Year	Estimated Cost	Actual Cost	Technical Santional No.	Administrative Santion No.	Work Order	Work Start Date	Working Agency	Estimated Measurement	MB Measurement	Actual Measurement	Work Quality	Observation	Recomandatio n	Photo
67	2.3.2019	KHASARMARI	L. B. S.	1	2017-18	0.073	0.073	744/31.5.2018	3987/1.6.2018	3252/27.11.2018	5.12.2018	NITESH JAGNALHE	L. 8, H. 1 MI	L. 8, H. 1 MI	L. 8, H. 1 MI	GOOD	CNB was repaired properly.	Regular Destilting. Removal of Vegetation.	
68	2.3.2019	KHASARMARI	L. B. S.	2	2017-18	0.073	0.073	744/31.5.2018	3987/1.6.2018	3252/27.11.2018	5.12.2018	NITESH JAGNALHE	L. 10, H. 1 MI	L. 10, H. 1 MI	L. 10, H. 1 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	
69	2.3.2019	KHASARMARI	L. B. S.	3	2017-18	0.073	0.073	744/31.5.2018	3987/1.6.2018	3252/27.11.2018	5.12.2018	NITESH JAGNALHE	L. 8, H. 1 MI	L. 8, H. 1 MI	L. 8, H. 1 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	
70	2.3.2019	KHASARMARI	L. B. S.	4	2017-18	0.021	0.021	745/31.5.2018	3987/1.6.2018	3252/27.11.2018	5.12.2018	NITESH JAGNALHE	L. 10, H. 1 MI	L. 10, H. 1 MI	L. 10, H. 1 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	
71	2.3.2019	KHASARMARI	L. B. S.	5	2017-18	0.021	0.021	745/31.5.2018	3987/1.6.2018	3252/27.11.2018	5.12.2018	NITESH JAGNALHE	L. 8, H. 1 MI	L. 8, H. 1 MI	L. 8, H. 1 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	
72	2.3.2019	KHASARMARI	L. B. S.	6	2017-18	0.031	0.031	746/31.5.2018	3987/1.6.2018	3252/27.11.2018	5.12.2018	NITESH JAGNALHE	L. 10, H. 1 MI	L. 10, H. 1 MI	L. 10, H. 1 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	









Sr. No.	Date Of Visit	Village	Work	No. Of Work	Sanction Year	Estimated Cost	Actual Cost	Technical Santional No.	Administrative Santion No.	Work Order	Work Start Date	Working Agency	Estimated Measurement	MB Measurement	Actual Measurement	Work Quality	Observation	Recomandatio n	Photo
73	2.3.2019	KHASARMARI	L. B. S.	7	2017-18	0.031	0.031	746/31.5.2018	3987/1.6.2018	3252/27.11.2018	5.12.2018	NITESH JAGNALHE	L. 8, H. 1 MI	L. 8, H. 1 MI	L. 8, H. 1 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	
74	2.3.2019	KHASARMARI	L. B. S.	8	2017-18	0.031	0.031	746/31.5.2018	3987/1.6.2018	3252/27.11.2018	5.12.2018	NITESH JAGNALHE	L. 10, H. 1 MI	L. 10, H. 1 MI	L. 10, H. 1 MI	GOOD	The gabion was properly formed.	Regular Destilting. Removal of Vegetation.	
75	2.3.2019	KHASARMARI	L. B. S.	9	2017-18	0.012	0.012	747/31.5.2018	3987/1.6.2018	3252/27.11.2018	5.12.2018	NITESH JAGNALHE	L. 8, H. 1 MI	L. 8, H. 1 MI	L. 8, H. 1 MI	GOOD	Useful for raising soil and waste.	Give more structure for water consevation.	
76	2.3.2019	KHASARMARI	L. B. S.	10	2017-18	0.012	0.012	747/31.5.2018	3987/1.6.2018	3252/27.11.2018	5.12.2018	NITESH JAGNALHE	L. 10, H. 1 MI	L. 10, H. 1 MI	L. 10, H. 1 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	
77	2.3.2019	KHASARMARI	FORM POND	14	2017-18	0.5	0.28	146/21.2.2017	540/22.2.2017	732/23.2.2017	21.2.2017	FORMAR	L.25,W.20,D.3 MI	L.25,W.20,D.3 MI	L.25,W.20,D.3 MI	GOOD	Helpful for supportive irrigation.	Regular Destilting. Removal of Vegetation.	
78	2.3.2019	KHASARMARI	Nala Deepening	1	2017-18	2.69	1.65	393/13.4.2017	548/18.4.2017	1365/17.5.2017	20.6.2017	ASWINI CONS.	L. 195 MI	L. 195 MI	L. 195 MI	GOOD	This work will benefit the farmers.	Regular Destilting. Removal of Vegetation.	









Sr. No.	Date Of Visit	Village	Work	No. Of Work	Sanction Year	Estimated Cost	Actual Cost	Technical Santional No.	Administrative Santion No.	Work Order	Work Start Date	Working Agency	Estimated Measurement	MB Measurement	Actual Measurement	Work Quality	Observation	Recomandatio n	Photo
79	2.3.2019	KHASARMARI	Nala Deepening	2	2017-18	1.97	1.33	394/13.4.2017	548/18.4.2017	1365/17.5.2017	29.5.2017	ASWINI CONS.	L. 185 MI	L. 185 MI	L. 185 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	
80	2.3.2019	KHASARMARI	Nala Deepening	6	2017-18	0.62	0.59	618/24.1.2018	771/1.2.2018	566/22.3.2018	21.4.2018	JAWED SHEKH	L. 240 MI	L. 240 MI	L. 240 MI	GOOD	Increase water level.	Handover to user group.	
81	2.3.2019	KHASARMARI	Nala Deepening	7	2017-18	0.66	0.63	619/24.1.2018	771/1.2.2018	599/22.3.2018	21.4.2018	JAWED SHEKH	L. 220 MI	L. 220 MI	L. 220 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	
82	2.3.2019	KHASARMARI	Nala Deepening	3	2017-18	0.41	0.32	615/24.1.2018	771/1.2.2018	600/22.3.2018	21.4.2018	HEMANT NETKE	L. 160 MI	L. 160 MI	L. 160 MI	GOOD	Increase ground water level.	Regular Destilting. Removal of Vegetation.	
83	2.3.2019	KHASARMARI	Nala Deepening	4	2017-18	0.39	0.26	616/24.1.2018	771/1.2.2018	600/22.3.2018	21.4.2018	PRANAY BHANDARKAR	L. 120 MI	L. 120 MI	L. 120 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	
84	2.3.2019	KHASARMARI	Nala Deepening	5	2017-18	0.83	0.78	617/24.1.2018	771/1.2.2018	600/22.3.2018	21.4.2018	PRANAY BHANDARKAR	L. 215 MI	L. 215 MI	L. 215 MI	GOOD	Proper Execution. Work is as per Technical Specification. Nala deepening is done.	Handover to user group.	







Sr. No.	Date Of Visit	Village	Work	No. Of Work	Sanction Year	Estimated Cost	Actual Cost	Technical Santional No.	Administrative Santion No.	Work Order	Work Start Date	Working Agency	Estimated Measurement	MB Measurement	Actual Measurement	Work Quality	Observation	Recomandatio n	Photo
85	2.3.2019	KHASARMARI	Dhaliche Bandh	1	2017-18	5.08	0.31	728/9.3.2018	1984/19.3.2018	1192/29.5.2018	20.6.2018	SANJAY BHISE	L. 908 MI	L. 908 MI	L. 908 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	
86	2.3.2019	KHASARMARI	Dhaliche Bandh	3	2017-18	3.39	0.15	730/9.3.2018	1984/19.3.2018	1192/29.5.2018	20.6.2018	SANJAY BHISE	L. 319 MI	L. 319 MI	L. 319 MI	GOOD	deepening of the drain will provide water for irrigation.	make provision to board.	
87	2.3.2019	PANJARLODHI	Dhaliche Bandh	1	2017-18	4.12	0.45	731/9.3.2018	1984/19.3.2018	1192/29.5.2018	14.6.2018	SANJAY BHISE	L. 1400 MI	L. 1400 MI	L. 1400 MI	GOOD	Decrease in soil runoff.		
88	2.3.2019	PANJARLODHI	Dhaliche Bandh	2	2017-18	3.52	0.67	732/9.3.2018	1984/19.3.2018	1192/29.5.2018	9.6.2018	SANJAY BHISE	L. 2215.96 MI	L. 2215.96 MI	L. 2215.96 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	
89	2.3.2019	PANJARLODHI	Dhaliche Bandh	3	2017-18	2.75	0.2	733/9.3.2018	1984/19.3.2018	1192/29.5.2018	17.6.2018	SANJAY BHISE	L. 534.24 MI	L. 534.24 MI	L. 534.24 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	
90	2.3.2019	PANJARLODHI	Gabion	1	2017-18	0.2	0.13	734/9.3.2018	1984/19.3.2018	1192/29.5.2018	1.6.2018	SANJAY BHISE	L. 10, W. 1 MI	L. 10, W. 1 MI	L. 10, W. 1 MI	GOOD	Useful for redusing water flow.	Regular Destilting. Removal of Vegetation.	






Sr. No.	Date Of Visit	Village	Work	No. Of Work	Sanction Year	Estimated Cost	Actual Cost	Technical Santional No.	Administrative Santion No.	Work Order	Work Start Date	Working Agency	Estimated Measurement	MB Measurement	Actual Measurement	Work Quality	Observation	Recomandatio n	Photo
91	2.3.2019	PANJARLODHI	Nala Deepening	1	2017-18	1.87	1.14	395/13.4.2017	548/19.4.2017	1365/17.5.2017	1.6.2017	ASWINI CONS.	L. 195 MI	L. 195 MI	L. 195 MI	GOOD	This work will benefit the farmers.	Regular Destilting. Removal of Vegetation.	
92	2.3.2019	PANJARLODHI	Nala Deepening	2	2017-18	1.9	1.14	396/13.4.2017	548/19.4.2017	1365/17.5.2017	1.6.2017	ASWINI CONS.	L. 195 MI	L. 195 MI	L. 195 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	
93	2.3.2019	PANJARLODHI	Nala Deepening	3	2017-18	2.83	1.69	397/13.4.2017	548/19.4.2017	1365/17.5.2017	14.6.2017	ASWINI CONS.	L. 195 MI	L. 195 MI	L. 195 MI	GOOD	Increase water level.	Handover to user group.	
94	2.3.2019	PARSODI GO.	FORM POND	124	2017-18	0.5	0.48	172/10.3.2017	773/10.3.2017	1029/10.3.2017	25.3.2017	FORMAR	L.25,W.20,D.3 MI	L.25,W.19,D.3 MI	L.25,W.19,D.3 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	
95	3.2.2019	JASAPUR	Dhaliche Bandh	1	2017-18	5.66	1.41	612/24.1.2018	771/1.2.2018	629/23.3.2018	5.4.2018	SANJAY BHISE	L. 4170 MI	L. 1340 MI	L. 1340 MI	GOOD	Increase ground water level.	Regular Destilting. Removal of Vegetation.	
96	3.2.2019	JASAPUR	Dhaliche Bandh	2	2017-18	3.69	0.86	612/24.1.2018	771/1.2.2018	629/23.3.2018	21.5.2018	SANJAY BHISE	L. 3260 MI	L. 1160 MI	L. 1160 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	



Sr. No.	Date Of Visit	Village	Work	No. Of Work	Sanction Year	Estimated Cost	Actual Cost	Technical Santional No.	Administrative Santion No.	Work Order	Work Start Date	Working Agency	Estimated Measurement	MB Measurement	Actual Measurement	Work Quality	Observation	Recomandation	Photo
97	3.2.2019	JASAPUR	Dhaliche Bandh	3	2017-18	4.6	0.89	612/24.1.2018	771/1.2.2018	629/23.3.2018	21.5.2018	SANJAY BHISE	L. 2068 MI	L. 510 MI	L. 510 MI	GOOD	Proper Execution. Work is as per Technical Specification. la deepening is done	Handover to user group.	
98	3.2.2019	AASHTA	Dhaliche Bandh	VIII/1	2017-18	7.13	0.4	717/26.2.2018	1563/5.3.2018	1144/17.5.2018	18.5.2018	SANJAY BHISE	L. 4170 MI	L. 1340 MI	L. 1340 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	
99	3.2.2019	AASHTA	Dhaliche Bandh	VIII/5	2017-18	7.28	0.68	717/26.2.2018	1563/5.3.2018	1144/17.5.2018	18.5.2018	SANJAY BHISE	L. 3260 MI	L. 1160 MI	L. 1160 MI	GOOD	deepening of the drain will provide water for irrigation.	make provision to board.	
100	3.2.2019	AASHTA	Dhaliche Bandh	VIII/2	2017-18	5.89	1.06	717/26.2.2018	1563/5.3.2018	1144/17.5.2018	30.5.2018	SANJAY BHISE	L. 2068 MI	L. 510 MI	L. 510 MI	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	
<b>144.838</b>																			
<b>59.854</b>																			




## Summary of Study Report with Pictures

Sr. No.	Date Of Visit	Village	Work	Number of Work	Sanction Year	Physical Target	Physical Achivment	Estimated Cost	Actual Coat	Technical Santional No.	Administrative Santion No.	Work Order	Work Start Date	Working Agency	Estimated Measurement	MB Measurement	Actual Measurement	Work Quality	Observation	Recomandation	Photo
1	4.3.2019	AALAGONDI	RECHARGE SAFT	5	2017-18	5	5	2.96	2.89	01/28-11-2017	469/18, 19-01-2018	335/2018, 26-02-2018	26/02/2018	NAGPUR	30 mtr Depth	30 mtr Depth	30 mtr Depth	GOOD	Increase ground water level.	The information panel should be set up.	
2	4.3.2019	KHASARMARI	RECHARGE SAFT	5	2017-18	5	5	2.96	2.89	02/28-11-2017	469/18, 19-01-2018	335/2018, 26-02-2018	26/02/2018	SHREE SAI BORVELS AND TUBELESS TEKA NAKA NAGPUR	30 mtr Depth	30 mtr Depth	30 mtr Depth	GOOD	Proper Execution. Work is as per Technical Specification.	Regular Destilting. Removal of Vegetation.	
3	4.3.2019	KINHAD MAKADI	RECHARGE SAFT	5	2017-18	5	5	2.96	2.89	03/28-11-2017	469/18, 19-01-2018	335/2018, 26-02-2018	26/02/2018	SHREE SAI BORVELS AND TUBELESS TEKA NAKA NAGPUR	30 mtr Depth	30 mtr Depth	30 mtr Depth	GOOD	WORK IS DONE PROPERLY	Regular Destilting. Removal of Vegetation.	
<b>TOTAL WORK</b>				<b>15</b>				<b>8.88</b>	<b>8.67</b>												





## Summary of Study Report with Pictures

Sr. No.	Date Of Visit	Village	Work	Lat/long	Sanction Year	Physical Target	Physical Achivment	Estimated Cost	Actual Coat	Technical Santional No.	Administrative Santion No.	Work Order	Work Start Date	Working Agency	Estimated Measurement	MB Measurement	Actual Measurement	Work Quality	Observation	Recomandation	Photo	
1	4.3.2019	Mohaagaon taallatule	K. t. repair	21.437/78.83	2017-18	-	-	14.75	9.42	314/20.03.2018	18/19.03.2018	1412/27/4/2018	02.05.2018	Vaishnav Kurhade	L-18,H-1.50 M	L-18,H-1.50 M	L-18,H-1.50 M	GOOD	This structure was plugged in half a meter.	Regular Destilting. Removal of Vegetation.		
Total							14.75	9.42														




## Summary of Study Report with Pictures

Sr. No.	Date Of Visit	Village	Work	No. Of Work	Sanction Year	Estimated Cost	Actual Cost	Technical Santional No.	Administrative Santion No.	Work Order	Work Start Date	Working Agency	Estimated Measurement	MB Measurement	Actual Measurement	Work Quality	Observation	Recomandatio n	Photo
1	03/12/2019	Kinhadmakdi	Bhumigat Bhandara, Richarge Soft v pit, nala	1	2017-18	8.17	6.28	01/01/2018	12/11/2017	17/2/2018	17/2/2018	Gram Panchayat	15m	15m	15m	Good	Motivate farmer for removal of silt, increase in crop yielding, and water storage.	Regular Destiliting. Removal of Vegetation.	
2	03/12/2019	Alagondi	Richarge soft & Pit, Trench galary	1	2017-18	3.32	1.44	01/01/2018	12/11/2017	17/2/2018	17/2/2018	Gram Panchayat	115/150mm, 330 m	115/150mm, 330 m	115/150mm, 330 m	Good	The work was done properly.	Make provision for display board.	



## Summary of Study Report with Pictures

Sr. No.	Date Of Visit	Village	Work	No. Of Work	Sanction Year	Estimated Cost	Actual Cost	Technical Santional No.	Administrative Santion No.	Work Order	Work Start Date	Working Agency	Estimated Measurement	MB Measurement	Actual Measurement	Work Quality	Observation	Recomandation	Photo
61	3.2.2019	AALAGONDI	C.N.B. REPERING	VI/1	2017-18	0.18	0.16	720/3.3.2018	1563/5.3.2018	1331/23.5.2018	24.5.2018	NISHANT DEWLHE	L.3,W.1.35,H.1.50 MI	L.3,W.1.35,H.1.50 MI	L.3,W.1.35,H.1.50 MI	Poor	The main wall and the side wall are broken.	Main wall and side wall should be repaired properly.	
62	3.2.2019	AALAGONDI	C.N.B. REPERING	VI/2	2017-18	0.29	0.18	721/3.3.2018	1563/5.3.2018	1331/23.5.2018	25.5.2018	NISHANT DEWLHE	L.4,W.1.35,H.1.50 MI	L.4,W.1.35,H.1.50 MI	L.4,W.1.35,H.1.50 MI	Poor	The main wall and the side wall are broken.	Main wall and side wall should be repaired properly.	